



Packaging Materials Included: return label, pouch with documents for U.S. Customs, box, and 1 air filled sleeve.



Insert device into opening of air filled sleeve.



Place the air filled sleeve into the box.



Insert power adapter into the box.



Secure box with 2" shipping tape (not provided)



Affix the return label to the box.



Drop your packaged device off at any FedEx Location