



Packaging Materials Included: return label, box, and 1 large air sleeve.



Insert device into opening of air filled sleeve.



Insert the air filled sleeve into the box.



Insert power adapter and cable into the box.



Secure box with 2" shipping tape (not provided)



Affix the return label to the box.



Drop your packaged device off at any FedEx Location